

SITE NAME:	Amoco		
SITE NUMBER:	0000025		
ADDRESS:	12707 Adams Road		
CITY:	Granger		
COUNTY:	St. Joseph		
SCORE:	26.02		
SCORE DATE:	January 1996		
CONTAMINANT TYPE:	Fuels and Solvents		
MEDIA AFFECTED:	Soil and Groundwater		
CONTACT PERSON:	Ken Gill at (317) 233-0404		
LAST REVISED:	February 2002		
CITE DIJOTO			

SITE PHOTO

STATUS: The site consists of a 40-acre petroleum product terminal that accepts refined petroleum products by means of a cross country underground pipeline. The terminal has operated since 1953. Over the years, many releases and spills of petroleum products have occurred. In August 1990, Amoco signed an Agreed Order (AO) with IDEM agreeing to perform an investigation and cleanup activities. Several remediation systems have been installed on the site and have been operating for many years to address the contamination in the soil and groundwater. Beneath the Amoco Oil terminal is a petroleum plume, with free product and dissolved petroleum compounds. This is being treated with pump and treat (air strippers) and with air sparging/vacuum extraction. This portion of the cleanup is expected to require many more years. The other groundwater problem is south of the terminal and extends south into a light industrial area and the Hinton-Bittersweet residential area. A large pump and treat system has been operating in this area for many years, and the groundwater is nearing the target cleanup levels.

This project is in the operations and maintenance stage of the cleanup. Routine water samples will be collected four (4) times annually from the monitoring wells, recovery wells and the residential and business wells until the site is judged to be cleaned.